

Final Reclamation Inspection

August 19, 2021

Operator: PDC ENERGY INC - 69175

Location ID: 332811

Inspection Document #: 7019000063

Weld County, CO

SWNW Section 28 T4N R66W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Korwick 5-28
Location ID: 332811



Photo 1. 2019 aerial imagery shows well head, access road and associated tank battery (north is up).

Inspection Photos
Location Name: Korwick 5-28
Location ID: 332811




Photo 2. Overview photo of well head, access road and reference area taken from the north side of well head facing south using a drone. Photo shows crop within well head appear consistent with adjacent reference area. Note: Lighter crop patch next to access road is not associated with oil/gas operations, likely a watering issue because of the size.

Inspection Photos
Location Name: Korwick 5-28
Location ID: 332811




Photo 3. Overview photo taken of tank battery and reference area (north is right). Note: Half of tank battery still remains, likely serving as access to eastern edge of field. New culvert has been constructed and feeds holding pond just south of the tank battery (highlighted in blue).



Inspection Photos
Location Name: Korwick 5-28
Location ID: 332811



Photo 4. Ground photo of culvert taken from southern portion of tank battery. Photo shows north to south running culvert that feeds into holding pond just south of tank battery disturbance pad.

Inspection Photos
Location Name: Korwick 5-28
Location ID: 332811



Photo 5. Ground photo taken from southeast corner of tank battery looking northwest. The ground is compacted and the vegetation resembles the reference areas nearby.