

Inspection Photos
Location Name: Simpson 24-11
Location ID: 313288



Photo 1. Overview of location taken facing northeast. Weeds on location.



Inspection Photos
Location Name: Simpson 24-11
Location ID: 313288



Photo 2. No bradenhead access apparent. Annual weeds on location.



Photo 3. Holes in produced water tank.



Inspection Photos
Location Name: Simpson 24-11
Location ID: 313288



Photo 4. Produced water label peeling.



Photo 5. Access road overgrown.