

Inspection Photos
Location Name: Simpson 24-10
Location ID: 313289



**Photo 1. Overview of location taken facing southwest.
Weeds on location.**



Inspection Photos
Location Name: Simpson 24-10
Location ID: 313289



Photo 2. Separator housing stored on location.



Photo 3. No bradenhead access apparent. Weeds on location.



Inspection Photos
Location Name: Simpson 24-10
Location ID: 313289



Photo 4. Tank label peeling.



Photo 5. Knocked over methanol tank.

