

Final Reclamation Inspection

August 17, 2021

Operator: K P KAUFFMAN COMPANY INC- #46290

Location ID: 319824

Inspection Document #: 697503167

Adams County, CO

NWSW Section 8 T1S R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: EDSTROM #1
Location ID: 319824



Photo 1. 2019 aerial imagery illustrates the well location, well location access road and associated offsite tank battery. There is a land use change to housing development within the yellow-dashed line.

Inspection Photos
Location Name: EDSTROM #1
Location ID: 319824



Photo 2. Photo taken from the western well location access road, facing East. Photo illustrates active construction operations are underway.

Inspection Photos
Location Name: EDSTROM #1
Location ID: 319824



Photo 3. Photo taken from the western well location access road, facing South. See comments under Photo 2.

Inspection Photos
Location Name: EDSTROM #1
Location ID: 319824



Photo 4. Photo taken from the associated offsite tank battery, facing South. Photo illustrates all equipment has been removed. See comments under Photo 2.

Inspection Photos
Location Name: EDSTROM #1
Location ID: 319824



Photo 5. Photo taken from the associated offsite tank battery, facing West. See comments under Photo 2.

Inspection Photos
Location Name: EDSTROM #1
Location ID: 319824



Photo 6. Photo taken from the associated offsite tank battery, facing Northwest. See comments under Photo 2.