

Inspection Photos
Location Name: Voloshin-Morton 1(-8)
Location ID: 312916



Photo 1. Overview of location taken facing south. No stormwater controls around soil pile from earthwork at wellhead.



Photo 2. Earthwork at wellhead with no stormwater controls.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources