

Inspection Photos
Operator: Kinder Morgan
API: 083-06437
Date: 8/31/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the western project area from the northwestern corner facing northward. Revegetation is progressing with rubber rabbitbrush, fourwing saltbush, Indian ricegrass, western wheatgrass, mountain pepperweed, sand dropseed, and crested wheatgrass.



Photo 3. View of the northern project area from the northwestern corner facing eastward.



Photo 4. View of area (approximately 8ft wide and 25ft long) in the northern project area with bare soils that needs to be stabilized with desirable vegetation. Soils may be impacted and need remediation.



Photo 5. View of reference area comprised of pinyon and juniper woodland with cliffrose, serviceberry, Indian ricegrass, Eaton's penstemon, and gambel oaks.