

Inspection Photos
Operator: Kinder Morgan
API: 083-06436
Date: 8/31/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the western project area from the southwestern corner facing northward. Revegetation is progressing with cliffrose, rubber rabbitbrush, Indian ricegrass, western wheatgrass, mountain pepperweed, sand dropseed, and crested wheatgrass.



Photo 3. View of the northern project area from the northwestern corner facing eastward.



Photo 4. View of reference area comprised of pinyon and juniper woodland with cliffrose, serviceberry, Indian ricegrass, Eaton's penstemon, and gambel oaks.