

Inspection Photos
Operator: Kinder Morgan
API: 083-06438
Date: 8/31/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the northern project area from the northwestern corner facing eastward. Revegetation is progressing with western wheatgrass, crested wheatgrass, blue grama, and rubber rabbitbrush.



Photo 3. View of the southern project area from the southeastern corner facing westward.



Photo 4. View of reference area comprised of open wheat field and pinyon/juniper mosaic (in background).