

Inspection Photos
Location Name: Champlin 248 Amoco A4
Location ID: 320091



Photo #1 Pump Jack



Photo #2 stained soil next to well head