

Final Reclamation Inspection

August 17, 2021

Operator: K P KAUFFMAN COMPANY INC- #46290

Location ID: 319993

Inspection Document #: 697503173

Adams County, CO

SESW Section 8 T1S R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: EDSTROM #3
Location ID: 319993



Photo 1. 2013 aerial imagery from COGCC GISOnline illustrates the well location has not been accurately recorded. The well location is over 100' off, the the north. The red arrow is pointing to the well.

Inspection Photos
Location Name: EDSTROM #3
Location ID: 319993



Photo 2. Photo taken from the southern well location access road, facing North. Photo illustrates the access road is not reflective of reference area vegetative levels. It does not appear any further reclamation activities were conducted per the previous corrective action inspection report. Reference area vegetation is to the right of the red-dashed line.

Inspection Photos
Location Name: EDSTROM #3
Location ID: 319993



Photo 3. Photo taken from the central well location access road, facing North. See comments under Photo 2.



Inspection Photos
Location Name: EDSTROM #3
Location ID: 319993



Photo 4. Photo taken from the western well location, facing East. See comments under Photo 2.

Inspection Photos
Location Name: EDSTROM #3
Location ID: 319993



Photo 5. Photo taken from the central well location, facing Southeast. See comments under Photo 2.



Inspection Photos
Location Name: EDSTROM #3
Location ID: 319993



Photo 6. Reference photo taken south of the well location, facing South. See comments under Photo 2.