

**Inspection Photos**  
**Location Name: Gladys #1**  
**API: 05-067-09099**



**Gladys #1 location photo.**



**Stained soil near well head.**

**Inspection Photos**  
**Location Name: Gladys #1**  
**API: 05-067-09099**



**Stained soil beneath truck load out valve.**



**Stained soil beneath truck load out valve. Valve is wet and stained.**