

Inspection Photos
Location Name: McCallum Unit 45
Location ID: 324606



Photo 1. Overview of location taken facing northwest.



Photo 2. No bradenhead access apparent.

