

Inspection Photos
Operator: Kinder Morgan
API: 083-06526
Date: 8/31/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the southern project area from the southeastern corner facing westward. Revegetation is progressing with rubber rabbitbrush, snakeweed, purple threawn, and Indian ricegrass.



Photo 3. View of the eastern project area from the southeastern corner facing northward.



Photo 4. View of reference area comprised of pinyon and juniper woodland with cliffrose, serviceberry, Indian ricegrass, Eaton's penstemon, and gambel oaks.