

Inspection Photos
Location Name: Moonshine 36-11-65
Location ID: 417959



Photo 1: Tank Battery Sign



Photo 2: Weeds

Inspection Photos
Location Name: Moonshine 36-11-65
Location ID: 417959



Photo 3: Weeds inside/outside tank battery berm



Photo 4: Weeds inside/outside berm

Inspection Photos
Location Name: Moonshine 36-11-65
Location ID: 417959




Photo 5: Weeds inside/outside berm



Photo 6: Weeds

Inspection Photos
Location Name: Moonshine 36-11-65
Location ID: 417959



Colorado Oil & Gas Conservation Commission

Photo 7: Weeds



Colorado Oil & Gas Conservation Commission

Photo 8: Weeds

Inspection Photos
Location Name: Moonshine 36-11-65
Location ID: 417959



Colorado Oil & Gas Conservation Commission

Photo 9: Debris



Colorado Oil & Gas Conservation Commission

Photo 10: Weeds; unused risers

