

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402726288

Date Received:

06/22/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 2 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

General

sjninspections@ikavenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693903248

Inspection Date: 04/28/2021

FIR Submit Date: 06/02/2021

FIR Status: _____

Inspected Operator Information:

Company Name: SIMCOE LLC

Company Number: 10749

Address: THREE ALLEN CENTER, 333 CLAY ST SUITE 3900

City: HOUSTON State: TX Zip: 77002

LOCATION - Location ID: 333634

Location Name: JONES, LAURANCE GAS UNIT A-N34N7W Number: 7NWSE County: LA PLATA

Qtrqr: NWSE Sec: 7 Twp: 34N Range: 7W Meridian: M

Latitude: 37.204826 Longitude: -107.646213

FACILITY - API Number: 05-067-00 Facility ID: 216248

Facility Name: LAURANCE JONES A Number: 1

Qtrqr: NWSE Sec: 7 Twp: 34N Range: 7W Meridian: M

Latitude: 37.204826 Longitude: -107.646213

CORRECTIVE ACTIONS:

2 ☒ CA# 151659

Corrective Action: Control weeds.

Date: 06/30/2021

Response: CA COMPLETED

Date of Completion: 06/14/2021

Operator Comment: weeds have been treated. see attached

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: CA completed - see attached

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Karin Rhodes

Signed: _____

Title: admin asst

Date: 6/22/2021 1:26:22 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

402726288	FIR RESOLUTION SUBMITTED
402726291	work completed weeds

Total Attach: 2 Files