

# Inspection Photos

API: 055-06291

Operator: PETROGLYPH OPERATING CO

Inspection Date: 8/31/2021



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06291 | Date: 8/31/2021

## Inspection Photos



**Photo 1.** Facing north along the access road. There was recent disturbance from what appears to be a surface owner water line.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06291 | Date: 8/31/2021

## Inspection Photos



**Photo 2.** A trench was dug through the center of the location. Red arrow points to area of the abandoned well.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06291 | Date: 8/31/2021

## Inspection Photos



**Photo 3.** Facing northwest. The location had been reclaimed and perennial vegetation has re-established throughout the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06291 | Date: 8/31/2021

## Inspection Photos



**Photo 4.** Facing north. The location had been reclaimed and perennial vegetation has re-established throughout the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06291 | Date: 8/31/2021

## Inspection Photos



**Photo 5.** View of perennial vegetation consisting of Western wheat, Sand drop seed, and Blue grama.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 055-06291 | Date: 8/31/2021