

Inspection Photos

API: 055-06179

Operator: PETROGLYPH OPERATING CO

Inspection Date: 8/31/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 055-06179 | Date: 8/31/2021

Inspection Photos



Photo 1. Facing south toward the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06179 | Date: 8/31/2021

Inspection Photos



Photo 2. Facing back north toward the former access road. The road is stabilized with perennial vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06179 | Date: 8/31/2021

Inspection Photos



Photo 3. Facing northeast at the location. Perennial vegetation has uniformly reestablished.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06179 | Date: 8/31/2021

Inspection Photos



Photo 4. Facing southwest at the location. Perennial vegetation has uniformly reestablished.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06179 | Date: 8/31/2021