

Interim Reclamation and Stormwater Inspection

August 26, 2021

Operator: HIGHPOINT OPERATING CORPORATION- 10071

Location ID: 432385

Inspection Document #: 697503188

Weld County, CO

SWSW Section 23 T6N R62W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources_S

Inspection Photos

Location Name: Pappenheim SW /6-62-23

Location ID: 432385



Photo 1. Drone aerial imagery illustrates the well location and the eastern location. Imagery illustrates the Operator has performed interim reclamation activities to reduce all areas only needed for production operations.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 697503188

Inspection Photos

Location Name: Pappenheim SW /6-62-23

Location ID: 432385



Photo 2. Drone aerial imagery illustrates the well location and the southern location. See comments under Photo 1.

Inspection Photos
Location Name: Pappenheim SW /6-62-23
Location ID: 432385



Photo 3. Drone aerial imagery illustrates the well location and the western location. See comments under Photo 1.

Inspection Photos

Location Name: Pappenheim SW /6-62-23

Location ID: 432385



Photo 4. Drone aerial imagery illustrates the multi-well location and the northern location. See comments under Photo 1.

Inspection Photos

Location Name: Pappenheim SW /6-62-23

Location ID: 432385



Photo 5. Photo taken from the southern interim reclamation area, facing West. Photo illustrates interim reclamation has been performed. Interim reclamation areas consisted mostly of desirable perennial vegetation establishment; however, location still consists of weedy, annual vegetation (Kochia and Russian thistle).



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 697503188

Inspection Photos

Location Name: Pappenheim SW /6-62-23

Location ID: 432385



Photo 6. Photo taken from the southeastern interim reclamation area, facing East. See comments under Photo 5.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 697503188

Inspection Photos

Location Name: Pappenheim SW /6-62-23

Location ID: 432385



Photo 7. Photo taken from the eastern interim reclamation area, facing North. See comments under Photo 5.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 697503188

Inspection Photos

Location Name: Pappenheim SW /6-62-23

Location ID: 432385



08.26.2021 10:26

Photo 8. Photo taken from the northern interim reclamation area, facing West. See comments under Photo 5.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 697503188

Inspection Photos

Location Name: Pappenheim SW /6-62-23

Location ID: 432385



Photo 9. Photo taken from the northern interim reclamation area, facing East. See comments under Photo 5.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 697503188

Inspection Photos

Location Name: Pappenheim SW /6-62-23

Location ID: 432385



Photo 10. Reference photo taken north of the interim reclamation area, facing North. See comments under Photo 5.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 697503188