

Inspection Photos
Location Name: Reugge 3R-4H-N165
Location ID: 331527



Pic 1 tanks



Pic 2 Separators

Inspection Photos
Location Name: Reugge 3R-4H-N165
Location ID: 331527



Pic 3 gas meter run, pig station.



Pic 4 ECD, VRU

Inspection Photos
Location Name: Reugge 3R-4H-N165
Location ID: 331527

Sep 1, 2021 at 1:10:09 PM
40.075203,-104.670301
262 County Road 41
Judson CO 80642
United States
COGCC



Pic 5 wellheads, natural gas generator.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources