


Inspection Photos
Location Name: Juanita State 1
Location ID: 320133

Sep 2, 2021 at 1:27:36 PM
39.914037,-104.505866
Bennett CO 80102
United States
COGCC



Pic 1 Wellhead weeds unmanaged on location

Sep 2, 2021 at 1:28:21 PM
39.914078,-104.505739
Bennett CO 80102
United States
COGCC



Pic 2 stained soil by pumpjack motor/Mechanical issue.

Inspection Photos
Location Name: Juanita State 1
Location ID: 320133

Sep 2, 2021 at 1:29:30 PM
39.913274,-104.507835
9301-40899 E 120th Ave
Bennett CO 80102
United States
COGCC



Pic 3 weeds unmanaged on location

Sep 2, 2021 at 1:29:54 PM
39.912865,-104.507866
9301-40899 E 120th Ave
Bennett CO 80102
United States
COGCC



Pic 4 trash on location

Inspection Photos
Location Name: Juanita State 1
Location ID: 320133



Pic 5 trash on loaction



Pic 6 spill from open top tank approx. 20'X14'

Inspection Photos
Location Name: Juanita State 1
Location ID: 320133



Pic 7 what appears to be dead animals in open top tank, oil present in open top tank, no netting, or content, placard, volume signs.



Pic 8 what appears to be dead animals in open top tank, oil present in open top tank, no netting, or content, placard, volume signs.

Inspection Photos
Location Name: Juanita State 1
Location ID: 320133



**Pic 9 no content, placard, or volume signs on open top tank,
with no netting.**