

Inspection Photos
Location Name: Ted & Hazel #11-1
API: 05-067-07171



Stained soil beneath AST load out valve. Weeds present within secondary containment berm. Contents are not labeled.



Ted & Hazel #11-1 wellhead and pump jack. Various unused, unlabeled containers stored within fencing.

Inspection Photos
Location Name: Ted & Hazel #11-1
API: 05-067-07171



Well head and surrounding area are stained with oil.



Weeds and unused containers present near pump jack.

Inspection Photos
Location Name: Ted & Hazel #11-1
API: 05-067-07171



Unused and unlabeled containers need to be removed.



Stained soil observed all around pump jack and well head.