

Location

Overall Good:

Signs/Marker:

	Type DRILLING/RECOMP		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:
 Corrective Action: Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 250623 Type: WELL API Number: 123-18426 Status: SI Insp. Status: WK

Workover

Comment: COGCC Inspection Report Summary
 On Thursday 9/2/21 at approximately 0758hrs I, Inspector Adam Burns, Conducted an on-site inspection at Dechant D 7-15 of Noble Energy Energy API # 05-123-18426 in Weld County, Colorado.
 While there, I observed a plugging operation. Ranger Energy Services was bleeding the well down to a combustor to start P/A procedures from the form 6.
 No violation of the COGCC rules were observed at the time of inspection.
 This is a summary of inspection report.

Corrective Action:

Date:

Completion

Operation:

Date Flowback:

Contractor:

Comment:

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699104367	Inspection Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5523473