

# Interim Reclamation and Stormwater Inspection

August 26, 2021

Operator: HIGHPOINT OPERATING CORPORATION- 10071

Location ID: 436773

Inspection Document #: 697503196

Weld County, CO

NWSW Section 34 T6N R62W

Chris Binschus  
Reclamation Specialist, COGCC




**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources<sub>S</sub>

Inspection Photos

Location Name: Fiducial /6-62-34\_35 NWSW

Location ID: 436773



**Photo 1.** Drone aerial imagery illustrates the well location and the eastern location. Imagery illustrates the Operator has performed interim reclamation activities to reduce all areas only needed for production operations.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 697503196

Inspection Photos

Location Name: Fiducial /6-62-34\_35 NWSW

Location ID: 436773



**Photo 2.** Drone aerial imagery illustrates the well location and the southern location. See comments under Photo 1.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 697503196

Inspection Photos  
Location Name: Fiducial /6-62-34\_35 NWSW  
Location ID: 436773



**Photo 3.** Drone aerial imagery illustrates the well location and the western location. See comments under Photo 1.

Inspection Photos

Location Name: Fiducial /6-62-34\_35 NWSW

Location ID: 436773



**Photo 4.** Drone aerial imagery illustrates the multi-well location and the northern location. See comments under Photo 1.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 697503196

Inspection Photos

Location Name: Fiducial /6-62-34\_35 NWSW

Location ID: 436773



**Photo 5.** Photo taken from the southern access road, facing North. Photo illustrates gully erosion in need of repair.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 697503196

Inspection Photos

Location Name: Fiducial /6-62-34\_35 NWSW

Location ID: 436773



**Photo 6.** Photo taken from the eastern interim reclamation area, facing Northeast. Photo illustrates interim reclamation has been performed. Desirable perennial vegetation establishment was observed; however, location still consists of weedy, annual vegetation (Kochia and Russian thistle).



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 697503196

Inspection Photos

Location Name: Fiducial /6-62-34\_35 NWSW

Location ID: 436773



**Photo 7.** Photo taken from the eastern interim reclamation area, facing South. See comments under Photo 6.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 697503196

Inspection Photos

Location Name: Fiducial /6-62-34\_35 NWSW

Location ID: 436773



**Photo 8.** Photo taken from the northern interim reclamation area, facing North. See comments under Photo 6.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 697503196

Inspection Photos

Location Name: Fiducial /6-62-34\_35 NWSW

Location ID: 436773



**Photo 9.** Photo taken from the northwestern interim reclamation area, facing South. See comments under Photo 6.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 697503196