

Inspection Photos
Location Name: Pismo East 35-26-23-2-1CH
Location ID: 440192



Photo 1: Location sign



Photo 2: Weeds

Inspection Photos
Location Name: Pismo East 35-26-23-2-1CH
Location ID: 440192



Photo 3: Weeds



Photo 4: Weeds

Inspection Photos
Location Name: Pismo East 35-26-23-2-1CH
Location ID: 440192



Photo 5: Weeds



Photo 6: Weeds

Inspection Photos
Location Name: Pismo East 35-26-23-2-1CH
Location ID: 440192



Photo 7: Weeds; unused equipment



Photo 8: Weeds; unused equipment

Inspection Photos
Location Name: Pismo East 35-26-23-2-1CH
Location ID: 440192



Photo 9: Stained soil



Photo 10: Stained soil

Inspection Photos
Location Name: Pismo East 35-26-23-2-1CH
Location ID: 440192



Photo 11: Stained soil




Photo 12: No NFPA placard

Inspection Photos

Location Name: Pismo East 35-26-23-2-1CH

Location ID: 440192



Photo 13: No NFPA placard



Photo 14: No NFPA placard



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Pismo East 35-26-23-2-1CH
Location ID: 440192



Photo 15: No NFPA placard



Photo 16: No NFPA placards