

Inspection Photos
Location Name: Hubbs #1
API: 05-067-09070



Hubbs #1 location photo.



Stained soil around well head.

Inspection Photos
Location Name: Hubbs #1
API: 05-067-09070



Stained soil beneath load out valve on AST.



Weeds and animal burrows within secondary containment berm.