



FLOWLINE ABANDONMENT FORM

SITE NAME: Rademacher 37-25							DATE: 9/2/2021	REM. PROJECT #: 2137067	WEATHER: 85 and sunny			
SITE DIRECTIONS: CR28/11 E .50, N.25,E into							CLIENT: Oxy					
LEGALS AND LAT/LONG: 40.192708,-104.946997							TASMAN PERSONNEL: Brandon VanHorn					
SOIL TYPES: Well Graded Gravel - GW							SURFACE GRADIENT: South					
SOIL SAMPLING							FACILITY INFRASTRUCTURE					
Date/Time	Soil Sample ID	PID (ppm)	Visual	Olfactory	Photo?	Grab or Lab Sample?	EQUIPMENT	Quantity				
							Above Ground Storage Tank (AST)					
9/2/2021 14:36	FL-B01@4'	1.1	No Staining	No Odor	Yes	N/A	Buried or Partially Buried Vessel					
							Separator					
							Emission Control Device (ECD)					
							Dump Line					
							Wellhead					
							Flowline	1				
							Other:					
							Soil Loads Removed					
							IMPACTED SOIL IDENTIFIED?					
							ESTIMATED VOLUME OF IMPACTS:					
							Date	Number	CY			
							Total Removed	0	0			
							Disposal Facility:					
							Groundwater Recovery					
							DATE GW ENCOUNTERED:			DEPTH:		
							GROUNDWATER IN CONTACT WITH IMPACTED SOIL?					
							LNAPL OR SHEEN OBSERVED ON GW?					
GROUNDWATER SAMPLING							Date			BBLS		
Date/Time	Groundwater Sample ID	Depth Collected	Turbid?	Sheen?	Odor?	Photo?						
							Total Removed			0		
							Disposal Facility:					



Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions:			

Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions:			

Photographic Log


Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions:			

Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:	
Notes/Conditions:			

Photographic Log


Equipment ID:		Equipment Type:		Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:		Material:	Volume:	Contents:	
Notes/Conditions:				Notes/Conditions:			