

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/30/2021

Submitted Date:

09/03/2021

Document Number:

701003510

**FIELD INSPECTION FORM**

Loc ID 433702 Inspector Name: Welsh, Brian On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10634  
Name of Operator: P O & G OPERATING LLC  
Address: 5847 SAN FELIPE SUITE 3200  
City: HOUSTON State: TX Zip: 77057

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

8 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Colotta, Wendy		wendy_colotta@pogresources.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
433709	WELL	SI	05/01/2019	OW	017-07761	Evan 1	TA

**General Comment:**

Initial SI/TA status MIT

**Location**

**Lease Road:**

Type	Access		
comment:	Dirt road through farm ground		
Corrective Action:			Date:

Overall Good:

**Signs/Marker:**

Type	BATTERY		
Comment:	Lease sign by tank		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Metal sign by tank		
Corrective Action:			Date:

**Emergency Contact Number:**

Comment:	<input type="text"/>	
Corrective Action:	<input type="text"/>	Date: _____

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No			
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 433709 Type: WELL API Number: 017-07761 Status: SI Insp. Status: TA

**Producing Well**

Comment: Tank batttery is 1800' E @ 38.850720/-102.369870

Corrective Action:

Date:

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Well is TA at time of inspection. MIRU EXTREME HEAT. LOAD CSG W/1BBL. PRESSURED UP TO 350 PSI. 5 MIN 330#. 10 MIN 330#. 15 MIN 330#. LOSS OF 20 PSI

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Other	Pass			

Comment: [Location and access are farmed over](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701003537	Form 21	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5524209">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5524209</a>