

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/07/2021

Submitted Date:

09/07/2021

Document Number:

699104378

FIELD INSPECTION FORM

Loc ID 326901 Inspector Name: Burns, Adam On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
246036	WELL	SI	01/01/2017	GW	123-13833	OCOMA II C31-9	TA

General Comment:

[This is a follow up to FIRR #402800929. CA has been corrected.](#)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 246036 Type: WELL API Number: 123-13833 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: T/A well is not connected to a flow line

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 04/23/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Tuesday 9/7/21 at approximately 0925hrs, I, Inspector Adam Burns, Conducted an on-site inspection to FIRR document #402800929 at Ocoma II C 31-9 of Noble Energy, at Location ID# 326901 in Weld County, Colorado. During this inspection the compliance issue has been corrected to comply with COGCC rules. See attached photos. This is a summary of inspection report.</p>	burnsa	09/07/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699104379	Inspection Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5525429