

Inspection Photos
Location Name: Margaret Twombly B 3
Location ID: 332957



Photo 1 WH sign emergency # faded sign lying on the ground

Photo 2 Dead weeds around WH

Inspection Photos
Location Name: Margaret Twombly B 3
Location ID: 332957



Photo 3 weeds around WH and pump jack

Photo 4 Dead weeds around pump jack

Inspection Photos
Location Name: Margaret Twombly B 3
Location ID: 332957



Photo 5 weeds around WH and pump jack

Photo 6 weeds around ancillary equipment