

Inspection Photos
Location Name: Martin T Hart B #2
Location ID: 332883



Photo 1 WH sign



Photo 2 WH

Inspection Photos
Location Name: Martin T Hart B #2
Location ID: 332883



Photo 3 Pump Jack



Photo 4 ancillary equipment

Inspection Photos
Location Name: Martin T Hart B #2
Location ID: 332883



Photo 5 Kerr McGee well