

Inspection Photos
Location Name: Yenom-Federal 1
Location ID: 312765



Photo 1. Overview of upper portion of location taken facing north.



Photo 2. Overview of lower portion of location taken facing northeast.



Inspection Photos
Location Name: Yenom-Federal 1
Location ID: 312765



Photo 3. Erosion off location perimeter.



Photo 4. Erosion off location perimeter.

Inspection Photos
Location Name: Yenom-Federal 1
Location ID: 312765



Photo 5. Erosion compromising berm and moving sediment to location perimeter.



Photo 6. Berm compromised by erosion.

Inspection Photos
Location Name: Yenom-Federal 1
Location ID: 312765



Photo 7. Erosion compromising berm and moving sediment to location perimeter.



Photo 8. Sediment moving off location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Yenom-Federal 1
Location ID: 312765



Photo 9. Sediment moving off location.



Photo 10. BMPs full of sediment in access road ditch.

Inspection Photos
Location Name: Yenom-Federal 1
Location ID: 312765



Photo 11. Sediment moving out of ditch, across access road, and off of access road.



Photo 12. BMPs full of sediment, sediment moving off access road.