

Inspection Photos

ID: 114302

Operator: PETROGLYPH OPERATING CO

Inspection Date: 8/31/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

ID: 114302 | Date: 8/31/2021

Inspection Photos



Photo 1. Drone aerial photo facing east toward the reclaimed LIVELY 35-09 BIG PIT.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 114302 | Date: 8/31/2021

Inspection Photos



Photo 2. Drone aerial photo facing west toward the reclaimed LIVELY 35-09 BIG PIT.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 114302 | Date: 8/31/2021

Inspection Photos




Photo 3. Facing northeast toward the LIVELY 35-09 BIG PIT area. There is desirable vegetation establishment throughout the location. There are also List B noxious weeds (Diffuse knapweed) shown at red arrow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 114302 | Date: 8/31/2021

Inspection Photos



Photo 4. Facing east at the location. Perennial vegetation is progressing throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 114302 | Date: 8/31/2021

Inspection Photos



Photo 5. Facing south at the location. Perennial vegetation is progressing throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 114302 | Date: 8/31/2021