

Inspection Photos

9/03/2021

Operator: CAERUS ENERGY SERVICES LLC -
10668

Location ID: 467272
Rio Blanco County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos
Operator Name: CAERUS ENERGY SERVICES LLC - 10668
Location ID: 467272



Photo 1: Photo taken from the south end of the Location, facing west. Photo shows control measures to contain drill cuttings is missing, or inadequate. Areas observed on the left of the photo include the perimeter stormwater controls (retention pond) for the Location