

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/25/2021

Submitted Date:

09/02/2021

Document Number:

688800976

**FIELD INSPECTION FORM**Loc ID 320878 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10753

Name of Operator: MORNINGSTAR PARTNERS LP

Address: 400 W 7TH ST

City: FORT WORTH State: TX Zip: 76102

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

5 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kittinger, Eric		ekittinger@mspartners.com	Principal Agent
Fischer, Alex		alex.fischer@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
480312	SPILL OR RELEASE	AC	07/28/2021		-	GAS GATHERING PIPELINE SYSTEM	EI

**General Comment:**

On August 25, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Morningstar Partners Gas Gathering Pipeline System Spill/Release Point ID #480312. Morningstar representatives were on site during this inspection.



**Environmental****Spills/Releases:**

Type of Spill: PRODUCED WATER

Estimated Spill Volume: 15

Comment: Refer to Spill/Release Point ID #480312 for more information regarding this release.

Corrective Action: Control and contain spills/releases and clean up per Rule 912.a.

Date: 10/02/2021

Reportable: YES

GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_

Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

Lat \_\_\_\_\_ Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Spill/Remediation:**

Comment: As discussed with on-site personnel, Spill/Release Point ID #480312 requires the Operator to submit a Form 27 Site Investigation and Remediation Workplan.

Corrective Action: Contact COGCC EPS staff regarding Rule 912.c.

Date: 09/06/2021

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
On August 25, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Morningstar Partners Gas Gathering Pipeline System Spill/Release Point ID #480312. Morningstar representatives were on site during this inspection. During this inspection, impacts from Spill/Release Point ID #480312 were observed from the release point on the west side of Highway 151, south to a low lying area, and through a culvert to the east side of the highway. From there impacts and indications of initial spill response efforts were observed between the highway and a dirt road. Impacts were observed on the east side of the dirt road and into a natural drainage where the observed impacts allegedly terminated. As discussed with on-site personnel, Spill/Release Point ID #480312 requires the Operator to submit a Form 27 Site Investigation and Remediation Workplan.	hughesjo	09/02/2021

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
402801070	INSPECTION SUBMITTED	<a href="http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5522654">http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5522654</a>
688800977	Inspection Photos	<a href="http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5522651">http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5522651</a>