

Final Reclamation Inspection

August 31, 2021

Operator: CRESTONE PEAK RESOURCES OPERATING LLC - 10633

Location ID: 336482

Inspection Document #: 697503211

Weld County, CO

SESE Section 19 T2N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: BANGERT #44-19
Location ID: 336482



Photo 1. Photo taken from the well location, facing Northeast. Photo illustrates the well location is reflective of reference crop areas.

Inspection Photos
Location Name: BANGERT #44-19
Location ID: 336482



Photo 2. Photo taken from the well location, facing East. See comments under Photo 1.

Inspection Photos
Location Name: BANGERT #44-19
Location ID: 336482



Photo 3. Photo taken from the well location, facing Southeast. See comments under Photo 1.

Inspection Photos
Location Name: BANGERT #44-19
Location ID: 336482



Photo 4. Photo taken from the associated offsite tank battery location, facing East.
Photo illustrates the tank battery location is still in use by another Operator, KPK.