

Interim Reclamation Inspection

August 31, 2021

Operator: K P KAUFFMAN COMPANY INC - 46290

API: 05-123-08017

Inspection Document #: 697503222

Weld County, CO

SESE Section 19 T2N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: NEFF #1
API: 05-123-10240



Photo 1. Photo illustrates Operator sign

Inspection Photos
Location Name: NEFF #1
API: 05-123-10240



Photo 2. Photo taken from the well location, facing South. Photo illustrates unmanaged weeds.