

Inspection Photos
Location Name: Castor LC 25-72HN
Location ID: 422133



Photo 1 – Wellhead



Photo 2 – Location Overview

Inspection Photos
Location Name: Castor LC 25-72HN
Location ID: 422133



Photo 3 – Tank Battery



Photo 4 – Tank Battery Sign



Inspection Photos
Location Name: Castor LC 25-72HN
Location ID: 422133



Photo 5 – Weeds in Interim Reclamation Area



Photo 6 – Weeds in Interim Reclamation Area

Inspection Photos
Location Name: Castor LC 25-72HN
Location ID: 422133



Photo 7 – Weeds in Interim Reclamation Area



Photo 8 – Weeds in Interim Reclamation Area

Inspection Photos
Location Name: Castor LC 25-72HN
Location ID: 422133



**Photo 9 – Weeds in Interim Reclamation Area – Lease Road
looking East**



Photo 10 – Weeds in Interim Reclamation Area

Inspection Photos
Location Name: Castor LC 25-72HN
Location ID: 422133



Photo 11 – Weeds in Interim Reclamation Area



Photo 12 – Weeds in Interim Reclamation Area

Inspection Photos
Location Name: Castor LC 25-72HN
Location ID: 422133



Photo 13 – Weeds in Interim Reclamation Area



Photo 14 – Weeds in Interim Reclamation Area