

**Inspection Photos**  
**Location Name: Castor 36-9-59 CTB**  
**Location ID: 434893**



**Photo 1 – Pumping Units**



**Photo 2 – Tank Battery**

Inspection Photos  
Location Name: Castor 36-9-59 CTB  
Location ID: 434893



Photo 3 – Tank Battery Sign

Photo 4 – Heater Treaters

**Inspection Photos**  
**Location Name: Castor 36-9-59 CTB**  
**Location ID: 434893**




**Photo 5 – Heater Treater**



**Photo 6 – Flare**

**Inspection Photos**  
**Location Name: Castor 36-9-59 CTB**  
**Location ID: 434893**



**Photo 7 – Stained Soil at South Heater Treater**

**Photo 8 – NFPA Label on South H2O Tank**

Inspection Photos  
Location Name: Castor 36-9-59 CTB  
Location ID: 434893



Photo 9 – Stained Soil at 7-36-9-59 Wellhead

Photo 10 – Wellhead Sign