

Inspection Photos
Location Name: Castor 36-11-9-59 CTB
Location ID: 427480



Photo 1 – Wellheads



Photo 2 – Tank Battery

Inspection Photos
Location Name: Castor 36-11-9-59 CTB
Location ID: 427480



Photo 3 – Tank Battery



Photo 4 – Location Sign at Entrance



Inspection Photos
Location Name: Castor 36-11-9-59 CTB
Location ID: 427480



Photo 5 – East Heater Treaters – Weeds



Photo 6 – West Heater Treater



Inspection Photos
Location Name: Castor 36-11-9-59 CTB
Location ID: 427480



Photo 7 – Compressor



Photo 8 – Gas Meters

Inspection Photos
Location Name: Castor 36-9-59 CTB
Location ID: 434893



Photo 9 – Flare



Photo 10 – Lease Road - Weeds

Inspection Photos
Location Name: Castor 36-9-59 CTB
Location ID: 434893



Photo 11 – Weeds in Pit Reclamation Area



Photo 12 – Weeds in Pit Reclamation Area

Inspection Photos
Location Name: Castor 36-9-59 CTB
Location ID: 434893



Photo 13 – Weeds in Pit Reclamation Area