

Inspection Photos
Location Name: REU 0681 1-23H2
Location ID: 449274



Photo 1. Sign at entrance incomplete. No sign at battery.



Photo 2. Wellhead sign incomplete.

