

Inspection Photos  
Operator: Logos Operating  
API: 067-05520  
Date: 9/7/2021



Photo 1. View of the project area from the eastern edge facing center.



Photo 2. View of the southern project area from the southeastern corner facing westward. Vegetation is largely kochia, similar to surrounding grazed pasture. Surface owner storage in southwestern corner of well pad.




Photo 3. View of weed debris around the well pad, and around the PBV (inset).



Photo 4. View of reference area comprised of grazed pasture.