

**Inspection Photos**  
**Operator: Logos Operating**  
**API: 067-09055**  
**Date: 9/7/2021**



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the southern project area from the southeastern corner facing westward. Revegetation is comprised of blue grama, western wheatgrass, fourwing saltbush, and rubber rabbitbrush.



Photo 3. View of the eastern project area from the southeastern corner facing northward.



Photo 4. View of reference area comprised of pinyon and juniper woodland with yucca, sagebrush, prickly pear, and Indian ricegrass.