

# Final Reclamation Inspection

September 7, 2021

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 322832

Inspection Document #: 697503230

Weld County, CO

NWNW Section 18 T4N R67W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation**  
**Commission**

Department of Natural Resources

Inspection Photos  
Location Name: STARCK #1  
Location ID: 322832



**Photo 1.** 2019 aerial imagery illustrates the well location, well location access road, and associated tank battery (red circles).



Inspection Photos  
Location Name: STARCK #1  
Location ID: 322832



**Photo 2.** Photo taken from the entrance of the well location access road, facing South. Photo illustrates the culvert has not been removed.



Inspection Photos  
Location Name: STARCK #1  
Location ID: 322832



**Photo 3.** Photo taken from the entrance of the well location access road, facing West. Photo illustrates final reclamation activities have not yet been completed.

Inspection Photos  
Location Name: STARCK #1  
Location ID: 322832



**Photo 4.** Photo taken from a portion of the well location access road, facing West. See comments under Photo 2.



Inspection Photos  
Location Name: STARCK #1  
Location ID: 322832



**Photo 5.** Photo taken of the associated offsite tank battery location, facing Southeast. Photo illustrates the tank battery is still use for other nearby wells.