

Attachment A



WELLHEAD ABANDONMENT FORM

SITE NAME: Von Feldt 13-12 Wellhead							DATE: 9/2/2021	REM. PROJECT #:	WEATHER: 80s and sunny	
SITE DIRECTIONS: CR47&CR70, E 0.1, N into							CLIENT: PDC			
LEGALS AND LAT/LONG: 40.495307, -104.618470							TASMAN PERSONNEL: David Vigil			
SOIL TYPES: Silty Sand - SM							SURFACE GRADIENT: Northeast			
SOIL SAMPLING							FACILITY INFRASTRUCTURE			
Date/Time	Soil Sample ID	PID (ppm)	Visual	Olfactory	Photo?	Grab or Lab Sample?	EQUIPMENT		Quantity	
							Above Ground Storage Tank (AST)			
9/2/2021 09:15	WH01 @ 6'	2.8	No Staining	No Odor	No	Lab	Buried or Partially Buried Vessel			
9/2/2021 11:38	FLR01 @ 3'	0.0	No Staining	No Odor	Yes	Lab	Separator			
9/2/2021 11:30	WH01-N @ 5'	0.1	No Staining	No Odor	Yes	Lab	Emission Control Device (ECD)			
9/2/2021 11:32	WH01-W @ 5'	0.0	No Staining	No Odor	Yes	Lab	Dump Line			
9/2/2021 11:34	WH01-S @ 5'	0.0	No Staining	No Odor	Yes	Lab	Wellhead		1	
9/2/2021 11:36	WH01-E @ 5'	0.0	No Staining	No Odor	Yes	Lab	Flowline		1	
9/2/2021 11:40	WHS01-N @ 0-6"	0.0	No Staining	No Odor	Yes	Grab	Other:			
9/2/2021 11:42	WHS01-E @ 0-6"	0.1	No Staining	No Odor	Yes	Grab	Soil Loads Removed			
9/2/2021 11:44	WHS01-S @ 0-6"	0.0	No Staining	No Odor	Yes	Grab	IMPACTED SOIL IDENTIFIED? Yes			
9/2/2021 11:46	WHS01-W @ 0-6"	0.1	No Staining	No Odor	Yes	Grab	ESTIMATED VOLUME OF IMPACTS:			
9/2/2021 10:50	FL01-01 @ 3'	0.1	No Staining	No Odor	Yes	Lab	Date		Number	CY
							9/2/2021		1	8
							Total Removed		1	8
							Disposal Facility: WM - Ault			
							Groundwater Recovery			
							DATE GW ENCOUNTERED:		DEPTH:	
							GROUNDWATER IN CONTACT WITH IMPACTED SOIL?			
							LNAPL OR SHEEN OBSERVED ON GW?			
GROUNDWATER SAMPLING							Date		BBLS	
Date/Time	Groundwater Sample ID	Depth Collected	Turbid?	Sheen?	Odor?	Photo?				
9/2/2021 13:00	GW01 @ 6'	6	Low Turbidity	None	None	Yes				
							Total Removed		0	
							Disposal Facility:			



Photographic Log

							
Equipment ID: WH01-S		Equipment Type:		Equipment ID: WH01-W		Equipment Type:	
Material:	Volume:	Contents:		Material:	Volume:	Contents:	
Notes/Conditions:				Notes/Conditions:			



Photographic Log

					
Equipment ID: WH01-N			Equipment Type:		
Material:	Volume:	Contents:	Equipment ID: WH01-E	Equipment Type:	
Notes/Conditions:			Notes/Conditions:		

Photographic Log

							
Equipment ID: FLR01		Equipment Type:		Equipment ID: WHS01-N		Equipment Type:	
Material:	Volume:	Contents:		Material:	Volume:	Contents:	
Notes/Conditions:				Notes/Conditions:			

Photographic Log

							
Equipment ID: WHS01-W		Equipment Type:		Equipment ID: WHS01-S		Equipment Type:	
Material:	Volume:	Contents:		Material:	Volume:	Contents:	
Notes/Conditions:				Notes/Conditions:			

Photographic Log

							
Equipment ID:WHS01-E		Equipment Type:		Equipment ID:GW04		Equipment Type:	
Material:	Volume:	Contents:		Material:	Volume:	Contents:	
Notes/Conditions:				Notes/Conditions:			

Photographic Log

									
						Equipment ID:		Equipment Type:	
						Material:	Volume:	Contents:	
						Notes/Conditions: cut and capped wellhead			
Equipment ID:		Equipment Type:							
Material:	Volume:	Contents:							
Notes/Conditions:									