

# Inspection Photos

9/09/2021

Operator: LARAMIE ENERGY LLC # 10433

Location ID: 335950

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: LARAMIE ENERGY LLC # 10433  
Location ID: 335950



**Photo 1:** Photos 1-2 taken from the northeast end of the Location, facing southeast, south to west. Photos provide overview of the Location.

Inspection Photos  
Operator Name: LARAMIE ENERGY LLC # 10433  
Location ID: 335950



**Photo 2:** See comments under photo 1.



Inspection Photos  
Operator Name: LARAMIE ENERGY LLC # 10433  
Location ID: 335950



**Photo 3:** Photos taken from the northern interim area. Photos show gully erosion degradation due to runoff from the Location. Rock-socks observed within the channel. Stormwater and erosion control measures observed are inadequate alone to control runoff from the Location in a manner that minimizes erosion and site degradation.



Inspection Photos  
Operator Name: LARAMIE ENERGY LLC # 10433  
Location ID: 335950



**Photo 4:** Photos taken from the northern interim area. Photos show gully erosion degradation due to runoff from the Location. Rock-socks observed within the channel. Stormwater and erosion control measures observed are inadequate alone to control runoff from the Location in a manner that minimizes erosion and site degradation.



Inspection Photos  
Operator Name: LARAMIE ENERGY LLC # 10433  
Location ID: 335950



**Photo 5:** Photos provide example of the interim areas on the Location; interim reclamation in process. No immediate issues observed.