





TANK BATTERY DECOMMISSIONING FORM

SITE NAME: Moser 11-28 OTA							DATE: 6/16/2021	REM. PROJECT #:		WEATHER: SUNNY100	
SITE DIRECTIONS: CR 43 AND 28 N 0.5, W0.2 INTO							CLIENT: Oxy				
LEGALS AND LAT/LONG: 40.19643644, -104.6691493							TASMAN PERSONNEL: Brandon LeVasseur				
SOIL TYPES: Clayey Sand - SC							SURFACE GRADIENT: East				
SOIL SAMPLING							FACILITY INFRASTRUCTURE				
Date/Time	Soil Sample ID	PID (ppm)	Visual	Olfactory	Photo?	Grab or Lab Sample?	EQUIPMENT		Quantity		
							Above Ground Storage Tank (AST)				
6/16/2021 13:52	PW-B01@3"	3.5	No Staining	No Odor	Yes	Lab	Buried or Partially Buried Vessel		1		
6/16/2021 13:53	PW-B02@3"	3.2	No Staining	No Odor	Yes	N/A	Separator		2		
6/16/2021 13:54	PW-BG01@3"	2.2	No Staining	No Odor	Yes	Lab	Emission Control Device (ECD)		1		
6/16/2021 13:55	DL-B01@3'	6.2	No Staining	No Odor	Yes	N/A	Dump Line		3		
6/16/2021 13:56	DL-B02@3'	3.2	No Staining	No Odor	Yes	N/A	Wellhead				
6/16/2021 13:57	DL-B03@3'	10.3	No Staining	No Odor	Yes	N/A	Flowline				
6/16/2021 13:58	SEP-B01@6"	2.5	No Staining	No Odor	Yes	Lab	Other:				
6/16/2021 13:59	SEP-B02@6'	2.0	No Staining	No Odor	Yes	Lab	Soil Loads Removed				
6/16/2021 14:00	SEP-B03@6"	2.1	No Staining	No Odor	Yes	Lab	IMPACTED SOIL IDENTIFIED?				
6/16/2021 14:01	SEP-B04@6"	5.1	No Staining	No Odor	Yes	Lab	ESTIMATED VOLUME OF IMPACTS:				
6/16/2021 14:02	MH-B01@6"	2.0	No Staining	No Odor	Yes	N/A	Date		Number	CY	
6/16/2021 14:03	ECD-B01@6"	1.7	No Staining	No Odor	Yes	N/A					
							Total Removed		0	0	
							Disposal Facility:				
							Groundwater Recovery				
							DATE GW ENCOUNTERED:		DEPTH:		
							GROUNDWATER IN CONTACT WITH IMPACTED SOIL?				
							LNAPL OR SHEEN OBSERVED ON GW?				
GROUNDWATER SAMPLING							Date		BBLS		
Date/Time	Groundwater Sample ID	Depth Collected	Turbid?	Sheen?	Odor?	Photo?					
							Total Removed		0		
							Disposal Facility:				

Photographic Log

							
Equipment ID:		Equipment Type:		Equipment ID:		Equipment Type:	
Material:		Volume:		Material:		Volume:	
		Contents:				Contents:	
Notes/Conditions:				Notes/Conditions:			

Photographic Log

							
Equipment ID:		Equipment Type:		Equipment ID:		Equipment Type:	
Material:		Volume:		Material:		Volume:	
Contents:				Contents:			
Notes/Conditions:				Notes/Conditions:			

Photographic Log

							
Equipment ID:		Equipment Type:		Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:		Material:	Volume:	Contents:	
Notes/Conditions:				Notes/Conditions:			

Photographic Log

									
						Equipment ID:		Equipment Type:	
						Material:	Volume:	Contents:	
						Notes/Conditions:			
Equipment ID:			Equipment Type:						
Material:	Volume:	Contents:							
Notes/Conditions:									