

Interim Reclamation Inspection

September 13, 2021

Operator: K P KAUFFMAN COMPANY INC - 46290

Location ID: 320506

Inspection Document #: 697503236

Adams County, CO

SESE Section 11 T1S R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: IVEY 16-11
Location ID: 320506



Photo 1. 2019 aerial imagery illustrates the well location (Ivey 16-11), well access roads and the associated tank battery (red circle). The yellow shaded area illustrates City of Thornton as the land owner. All property damage was observed on City of Thornton land.



Rutted area

Photo 2. Drone aerial imagery taken from the well location, facing West. Photo illustrates the approximate property line and some of the observed rutted areas. Photo also illustrates unmanaged weeds around the tank battery location- see Photos 9&10.





Photo 3. Drone aerial imagery taken from the well location, facing North. See comments under Photo 2.



Ruttled area

Photo 4. Drone aerial imagery taken from the well location, facing East. See comments under Photo 2.



Photo 5. Photo taken from the southeastern rutted area, facing North. Ruts have damaged areas where it appears City of Thornton has recently conducted seeding on much of the area adjacent to the well location.



Photo 6. Reference photo taken from an adjacent area illustrating new vegetative growth from a recent seeding.

Inspection Photos
Location Name: IVEY 16-11
Location ID: 320506



Photo 7. Photo taken from the well location, facing South. Photo illustrates unused equipment.



Photo 8. Photo taken from the well location, facing South. See comments under Photo 7.

Inspection Photos
Location Name: IVEY 16-11
Location ID: 320506



Photo 9. Photo taken from the associated tank battery, facing West. Photo illustrates unmanaged weeds.



Photo 10. Photo taken from the associated tank battery, facing West. See comments under Photo 9.

