

# Interim Reclamation Inspection

September 13, 2021

Operator: K P KAUFFMAN COMPANY INC - 46290

Location ID: 317831

Inspection Document #: 697503239

Weld County, CO

NWSE Section 20 T2N R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation  
Commission**

Department of Natural Resources



**Photo 1.** Photo taken from the well location, facing West. Photo illustrates unmanaged noxious (Musk thistle) and undesirable weeds. Musk thistle has already set seed.

Inspection Photos  
Location Name: NESSU 15  
Location ID: 317831



**Photo 2.** Photo taken from the well location, facing West. See comments under Photo 1.



**Photo 3.** Photo taken from the well location, facing West. See comments under Photo 1.