

Inspection Photos
Location Name: Newton #1
Location ID: 319025



Photo 1 WH sign



Photo 2 WH

Inspection Photos
Location Name: Newton #1
Location ID: 319025



Photo 3 TB sign



Photo 4 TB



Inspection Photos
Location Name: Newton #1
Location ID: 319025



Photo 5 Gas Meter Run




Photo 6 Card indicates current calibration

Inspection Photos
Location Name: Newton #1
Location ID: 319025



Photo 7 Weeds have been cut around ECD



Photo 8 Horizontal Heated Separator