

# PHOTOGRAPHIC LOG

<b>Project Name:</b> HSC 1	<b>Site Location:</b> Laramie – Horseshoe Canyon 1 P&A Facility Closure	<b>Project No.</b> 021-133
<p><b>Facility:</b> HSC 1</p> <p><b>Description:</b> Wellhead (Facing Southwest)</p>		
<p><b>Facility:</b> HSC 1</p> <p><b>Description:</b> Tank surface (Facing North).</p>		

# PHOTOGRAPHIC LOG

<b>Project Name:</b> HSC 1	<b>Site Location:</b> Laramie – Horseshoe Canyon P&A Facility Closure	<b>Project No.</b> 021-133
<p><b>Facility:</b> HSC 1</p> <p><b>Description:</b> Separator/Meter Building surface. Tank/Historic Pit depression behind (Facing North).</p>	 <p>A wide-angle photograph of a dirt and gravel area. Two yellow survey stakes are visible, one on the left and one on the right. A dark pipe or hose runs across the ground. The background shows a rocky, vegetated hillside.</p>	
<p><b>Facility:</b> HSC 1</p> <p><b>Description:</b> Wellhead/Flowline Excavation (Facing West).</p>	 <p>A photograph showing a deep excavation of a wellhead. The wellhead is a complex metal structure with a red cap, partially buried in the earth. The surrounding area is filled with loose soil and rocks. A yellow survey stake is visible in the background.</p>	

# PHOTOGRAPHIC LOG

<b>Project Name:</b> HSC 1	<b>Site Location:</b> Horseshoe Canyon 1 P&A Facility Decommission	<b>Project No.</b> 021-133
<p><b>Facility:</b> HSC 1</p> <p><b>Description:</b> Tank/Historic Pit excavation (Facing North).</p>		
<p><b>Facility:</b> HSC 1</p> <p><b>Description:</b> Pit excavation – Bedrock Refusal with heavy equipment.</p>		